

Axis L DL Recessed Installation Manual


Step 1: Make a cutout on the ceiling as per the dimensions below.



Step 2: Take out main supply cable through ring..




Main Power Supply (120V)




Step 3: Connect the power cable with Driver.


Step 4: Close Driver Cover.




Step 5: Then connect the driver and fixture with help of quick connector




Step 6: Press the toggles for insert into cutout.



Step 7: Installation is completed. Lights ON.



Step 8: You can adjust the fixture up to ± 30◦.



Step 9: You can rotate the fixture with your finger up to 355°.

Rotation: 355◦

