


Perdu 4X Linear Surface Installation Manual


Step 1: Ensure the main power is turned off. Screw the ceiling plate to ceiling as shown in fig below



Step 2: Connect the driver to the light fitting using the quick connector then attach the light fitting to the ceiling plate using magnet which is attached to the rear side of light fitting.







Installation is complete. Lights can be turned on!